

Category	Comments
Size of Site	4.55 Acres
Size of building(s)	Stadium - 557 SM
	Field House - 139 SM
Age of Building	Stadium - 1929
	Field House - Unknown
Structure of the Building	Stadium:
	Reinforced concrete construction
	Concrete floor slabs
	Concrete block masonry walls
	Open Air Seating, constructed of 2x10 planks mounted on steel brackets
	Wall Finishes - Exterior painted parging. Washrooms are half wall tile, painted concrete blocks on upper half
	Floor Finishes - Washroom floor is stone tile
	Doors - steel
	Field House:
	Concrete block structure
	Brick Masonry
	Floor Finishes - Painted concrete in washrooms. Shower area is tile
Electrical Services	Stadium:
	Supplied to the building by utility provider. 600A service
	Interior lighting system - fluorescent lighting fixtures mounted to ceilings in under seat rooms
	Exterior Lighting system (8) tower light poles, quartz-halide lighting
	Telecommunications - supplied to the building by utility provider
	Field House:
	Supplied to the building by City of Windsor Maintenance Depot to south of building (shared service)
	Entire Site:
	No Fire Alarm system
	No Local Area Network
	No Public Address system
	No Security Alarm
Mechanical Services	Stadium:
	Washrooms contain exhaust fans
	Domestic hot water provided by electrical hot water heater
	Electric Coil Fan heaters
	Field House:
	Washrooms contain exhaust fans
Natural Gas	No Natural Gas Service
Water	Stadium:
	Supplied to the building by utility provider
	Field House:
	Supplied to the building by City of Windsor Maintenance Depot to south of building (shared service)
Sanitary Services	Connected to municipal services