

Category	Comments
Size of Site	8.7 acres
Size of building	One Storey - 5,106 SM (Partial Basement)
Additions	Original Building 1936 - SM 1225
	Addition #1 - 1953 - SM 1938
	Addition #2 - 1962 - SM 1950
	Addition #3 - 1975 - SM 450
	Addition #4 - 1991 - SM 944
	Addition #5 - 1992 - SM 339
Structure of the Building	Concrete foundation walls on Concrete spread footings
	Concrete slab on grade foundation floor
	Concrete masonry load bearing walls and concrete masonry columns.
	Steel framed roof with steel roof decking. Wood trusses and plywood for roofing in addition #4.
	Brick veneered concrete block
	Windows - a mixture of insulating glazing units and single glazed units
	Hollow metal doors and frames on the exterior. Wood doors on the interior.
	Floor finishes - terrazzo, resilient tile flooring, porcelain tile, carpet, hardwood floor and sealed concrete.
	Wall finishes - painted concrete block, painted gypsum wall board and ceramic wall tile
	Ceiling finishes - suspended acoustical ceiling tile, painted gypsum wallboard and painted overhead structure.
Electrical Services	Supplied to the building by utility provider
	Main Service - 120/208 V - 1200 amp
	Exit signs to indicate means of egress
	Battery operated emergency lights
	Interior lighting system - fluorescent light fixtures
	Exterior lighting system - wall and soffit mounted fixtures
	Fire Alarm system - Zoned and monitored by an outside agency
	Fire suppression and sprinkler system throughout
	Telephone service in office area
	Local Area Network throughout building
	Public Address system present
	Security Alarm monitored by an outside agency
Mechanical Services	conditioned air is supplied to the office and the gym by three rooftop units.
	three natural gas fire boilers for heating through a mixture of radiation and unit ventilators.
	Domestic hot water supplied by gas-fired tank type heater.
	Mixture of digital and pneumatic controls
Natural Gas	Supplied to the building by utility provider
Water	Supplied to the building by utility provider
Sanitary Services	Connected to municipal services