

GREATER ESSEX COUNTY

DISTRICT SCHOOL BOARD

Date: December 13, 2016

School Information Profile

Eastwood Public School 3555 Forest Glade Drive Windsor, Ontario N8R 1X8

Facility Profile

Site plan and floor plan(s) (or space template) of the school with the date of school construction and any subsequent additions

Site Plan (page 6) and Floor Plan (page 7) attached

Constructed in 1976 (2,771 sm)

Addition in 1997 (732 sm)

School attendance area (boundary) map

Map is attached (page 8)

Context map (or air photo) of the school indicating the existing land uses surrounding the school Map is attached (page 9)

Planning map of the school with zoning Map is attached (page 10)

Size of the school site (acres or hectares) = 2.585 ha

Building area (square feet or square metres) = 3,503 sm

Number of portable classrooms = 0

Number and type of instructional rooms as well as specialized classroom teaching spaces (e.g., science lab, tech shop, gymnasium, etc.)

SFIS Room Summary attached (page 11 - 12)

Area of hard surfaced outdoor play area and/or green space, the number of play fields, and the presence of outdoor facilities (e.g., tracks, courts for basketball, tennis, etc.)

Hard Surface = 2,508 sm (hard surface)

Paved running track

Soccer fields

Basketball nets

Baseball backstop

Ten-year history of major facility improvements (item and cost)

HVAC Upgrade \$125,000

Kiss and Ride \$91,000

Roofing \$593,000

Painting \$36,674

Door Replacement \$7,300

Projected five-year facility renewal needs of school (item and cost)

VFA Renewal List attached (pages 13 - 23)

Current Facility Condition Index (FCI) with a definition of what the index represents:

Date: December 13, 2016

FCI = 40%

Facility Condition Index (FCI) = Cost of Renewal Need
Asset Replacement Value

Student distance to school in kilometres

Minimum: 0.03 km Maximum: 9.23 km Average: 0.92 km

Percentage of students, under the school board policy that are:

eligible for transportation: 27% not eligible for transportation: 63% longest bus ride to school: 5 mins shortest bus ride to school: 1 min

average length of bus ride time: 2.8 mins

School operational costs e.g. custodial, utility and maintenance (totals, per square foot, and per student)

Total costs = \$ 253,232 Costs per student = \$962.86 Costs per sq metre = \$72.29

Number of parking spaces on site at the school, an assessment of the adequacy of parking, and bus/car access and egress

28 Parking Spots – City Bylaw requires 33 – Parking is not adequate.

Kiss and ride on site

No busbay

Measures that the school board has identified and/or addressed for accessibility of the school for students, staff, and the public with disabilities (i.e., barrier-free)

Fully accessible, no barrier free washroom, automatic door opener on front door.

On-the-ground (OTG) capacity, and surplus/shortage of pupil places

OTG = 392

2016/17 ADE = 271

surplus spaces = 121

Instructional Profile

Date: December 13, 2016

Describe the number and type of teaching staff, non-teaching staff, support staff, itinerant staff, and administrative staff at the school:

- 1.0 Principal
- 0.25 Vice-Principal
- 16.5 Currently Teaching Staff
- 2.0 Early Childhood Educator
- 1.0 Child and Youth Worker
- 2.0 Educational Assistants
- 1.0 Developmental Service Workers
- 2.0 Custodians
- 1.0 Secretary

Itinerate Staff:

Speech and Language: 0.5 days per week Educational Coordinator: 0.5 days per week Educational Psychologist: 0.5 days per week

Social Worker: 0.5 days per week

ESL: 2 periods per day

Describe the course and program offerings at the school:

JK to 8 English school offering standard elementary school programming

SERR LST

ESL Support

FSL (Core)

Music

Physical Education & Health

Describe the specialized service offerings at the school (e.g., cooperative placements, guidance counseling, etc.)

Before and After school day care

Community use of gym and soccer field in evening and on weekends

Nutrition Program

Co-op Placement through Riverside Secondary School

Involved in Reciprocal Partnership with China

International Associate Teachers for Faculty of Education

Zones Room

ESL Itinerate Staff

Curiosity Club

K – 8 Inquiry Math Learning through University of Windsor

Empower Reading from Sick Kids

SWIS Worker

Current grade configuration of the school JK – Grade 8 Current grade organization of the school (e.g., number of combined grades, etc.) # of combined grades = 8 # of straight grades = 3 Number of out of area students - 31 Utilization factor/classroom usage: 2 JK/SK classrooms 2 special education classroom (plus one LST office) 9 regular classrooms 1 French room 1 music room 1 drama room/CYW 3 offices 1 staffroom with photocopier 1 custodial room 1 room utilized by YMCA Summary of five previous years' enrolment and 10-year enrolment projection by grade and program Summary attached (page 24) Current extracurricular activities: Athletics: Cross Country, soccer, volleyball, basketball, track and field, baseball, badminton Band Choir **Knitting Club ECO** schools Social Justice Pangea (Student Leadership)

Other School Use Profile

Date: December 13, 2016

Current non-school programs or services resident at or co-located with the school as well as any revenue from these non-school programs or services and whether or not it is at full cost recovery

None

Current facility partnerships as well as any revenue from the facility partnerships and whether or not it is at full cost recovery

None

Community use of the school as well as any revenue from the community use of the school and whether or not it is at full cost recovery

Projected September 2016-June 2017 School Rental Permitted Hours	
EASTWOOD PUBLIC SCHOOL	Hours
Gym	108
Classrooms	0
Total	108

Projected September 2016-June 2017 School Rental Revenue	
EASTWOOD PUBLIC SCHOOL	
Rent Paid by rental groups	\$ 487
Covered by the CUS grant	\$1957
Other fees	\$ 0
Total	\$2444

Community Use Overview:

The gym is used for recreational basketball, volleyball, soccer and Girl Guides.

Availability of before and after school programs or services (e.g., child care) as well as any revenue from the before and after school programs and whether or not it is at full cost recovery


YMCA – Before and After School – Full Cost Recovery


Lease terms at the school as well as any revenue from the lease and whether or not it is at full cost recovery


None


Description of the school's suitability for facility partnerships

The school is currently suitable for facility partnerships.



















Page 1 of 2

GiulianaHinchliffe - Wed Nov 30 08:14:09 EST 2016 Data reflects the 2016-2017 Year 692 Eastwood Public School Inventory Data - Room Summary

Permanent S	Space Room Summ	ary		,			
	2016-2017	OTG 🗸		1998-199	99 OTG 🗸	Change	e Year
Room Number	Space Type	Current Use	Loading	Room Number	Space Type	Current Use	Loading
01	Classroom	Classroom	23.0				
03	Classroom	Classroom	23.0				
103	Classroom	Classroom	23.0				Ĭ
105	Classroom	Classroom	23.0				
112	Classroom	Classroom	23.0				Ti .
East.B	Classroom	Classroom	23.0				
East.C	Classroom	Classroom	23.0				
North.A	Classroom	Classroom	23.0		İ		İ
North.B	Classroom	Classroom	23.0				i i
North.C	Classroom	Classroom	23.0				
South.A	Classroom	Classroom	23.0		Ĭ		Ť
South.B	Classroom	Classroom	23.0		İ		Ti .
South.C	Classroom	Classroom	23.0		i		İ
GYM	General Purpose Room	General Purpose Room	0.0				
110	Kindergarten	Junior / Senior Kinderg.	26.0				
111	Kindergarten	Junior / Senior Kinderg.	26.0				
LIBRARY	Library Resource Centre	Library Resource	0.0				
04	Music Rm (Instrumental)	Music (Instrumental)	0.0				
02	Science Room	Resource-French	23.0		İ	İ	İ
104	Special Ed.	Special Education	9.0				
East.A	Special Ed.	Special Education	9.0				
OF6	Seminar Room	Resource- General	0.0				
		Staff					

https://sfis.edu.gov.on.ca/FacilityInventory/Rooms.aspx?mode=sum&sfisid=692

11/30/2016

Page 2 of 2

OF5	Seminar Room	Work/Lounge	0.0		
STAFF	Staff Work Rm./Lounge	Staff Work/Lounge	0.0		
		2016 OTG	392	2016 NPP	0



Requirement List Report By Category

Board Name: Greater Essex County District School Board
Campus Name: Eastwood Public School, Campus ID 5755
Asset Name: Eastwood Public School, Building ID 5755-1-5755-1

Reporting Currency: CAD
Prime System: All
Requirement Priority: All
Requirement Category: All
Requirements Included: All

Category	Requirement Name	Prime System	Priority	System Group	Action Year	Action Date	Finish Date	Status	Linked System	Requirement Cost
Major Repair	Major Repair [Playing Fields - Unpaved Playing Field]	G2040 - Site Development	3 - Year three	Site	2015	Jan 1, 2015		Open	Playing Fields - Unpaved Playing Field	32,760
Major Repair	Repair [Underground Utilities]	G30 - Site Mechanical Utilities	3 - Year three	Site	2015	Jan 1, 2015		Open	Underground Utilities	393,120
Major Repair										425,880

Copyright $\,^{\circlearrowright}$ 2016 VFA, Inc. All rights reserved.

Nov 30, 2016 7:52:55 AM

Page 1 of 11



Category	Requirement Name	Prime System	Priority	System Group	Action Year	Action Date	Buish Date	Status	Linked System	Requirement Cost
Program/ Upgrade	Functional Events [General Purpose Room - Original Building]	F106007 - General Purpose Room*	7 - Not time critical	None Selected	2015	Jan 1, 2015	,	Open	General Purpose Room - Original Building	0
Program/ Upgrade	Functional Events [Library Resource Centre - Original Building]	F106003 - Library Resource Centre*	7 - Not time critical	None Selected	2015	Jan 1, 2015		Open	Library Resource Centre - Original Building	0
Program/Upg	rade									0
Replacement	Air Distribution, Heating & Cooling - Original Building Renewal	D304001 – Distribution Systems – Air Distribution, Heating & Cooling	4 - Year four	No ne Selected	2015	Jan 4, 2015		Open	Air Distribution, Heating & Cooling - Original Building	351,577
Replacement	Air Handling Units - Original Building Renewal	D304008 - Air Handling Units	4 - Year four	None Selected	2015	Apr 4, 2015		Open	Air Handling Units - Original Building	76,440
Replacement	Auxiliary Equipment - Original Building Renewal	D3020 - Heat Generating Systems	5 - Year five	HVAC System	2016	Jan 4, 2016		Open	Auxiliary Equipment - Original Building	9,306
Copyright © 20)16 VFA, Inc. All rights res	erved.		1	Tov 30, 2016	7:52:55 AM				Page 2 of 11



Category	Requirement Name	Prime System	Priority	System Group	Action Year	Action Date	Mnish Date	Status	Linked System	Requirement Cost
Replacement	Branch Wiring - Original Building Renewal	D502001 - lighting and Branch Wiring - Branch Wiring	6 - Year one SPW	None Selected	2016	Sep 18, 2016	,	Open	Branch Wiring - Original Building	378,043
Replacement	Ceiling Finishes - Gypsum Board Ceiling - Original Building Renewal	C303003 - Ceiling Finishes - Gypsum	6 - Year one SPW	None Selected	2016	Nov 21, 2016		Open	Ceiling Finishes - Gypsum Board Ceiling - Original Building	20,838
Replacement	Ceiling Finishes - Suspended Acoustic Panel Ceiling - Original Building Renewal	C303004 - Ceiling Finishes - Acoustic	5 - Year five	None Selected	2015	Nov 21, 2015		Open	Ceiling Finishes - Suspended Acoustic Panel Ceiling - Original Building	174,743
Replacement	Ceiling Finishes - Painted Ceiling Structures - Original Building Renewal	C303006 - Ceiling Finishes - Paint	5 - Year five	None Selected	2015	Nov 21, 2015		Open	Ceiling Finishes - Painted Ceiling Structures - Original Building	21,841
Replacement	Chilled Water Systems - Original Building Renewal	D303012 - Chilled Water Systems - Cooling Tow <i>e</i> rs	6 - Year one SPW	None Selected	2020	Jan 4, 2020		Open	Chilled Water Systems - Original Building	59,592
Replacement	Controls & Instrumentation - Addition 1 Renewal	D3060 - Controls and Instrumentation	6 - Year one SPW	HVAC System	2020	Jan 4, 2020		Open	Controls & Instrumentation - Addition 1	38,933
Copyright © 20	016 VFA, Inc. All rights re	served.			Nov 30, 2016	7:52:55 AM				Page 3 of 11



Category	Requirement Name	Prime System	Priority	System Group	Action Year	Action Date	Rnish Date	Status	Linked System	Requirement Cost
Replacement	Controls & Instrumentation - Original Building Renewal	D3060 - Controls and Instrumentation	6 - Year one SPW	HVAC System	2018	Jan 4, 2018		Open	Controls & Instrumentation - Original Building	147,387
Replacement	Domestic Water Distribution - Original Building Renewal	D202030 - Domestic Water Distribution - Natural Gas DWH	4 - Year four	None Selected	2015	Jan 4, 2015		Open	Domestic Water Distribution - Original Building	10,865
Replacement	Domestic Water Distribution - Original Building Renewal	D202001 - Domestic Water Distribution - Pipes and Pittings	4 - Year four	None Selected	2015	Jan 4, 2015		Open	Domestic Water Distribution - Original Building	180,154
Replacement	Exhaust Systems - Original Building Renewal	D304007 - Distribution Systems - Exhaust Systems	4 - Year four	None Selected	2015	Jan 4, 2015		Open	Exhaust Systems - Original Building	49,920
Replacement	Exterior Doors - Hollow Metal - Addition 1 Renewal	B2030 - Exterior Doors	6 - Year one SPW	Exterior Enclosure	2017	Nov 21, 2017		Open	Exterior Doors - Hollow Metal - Addition 1	9,360
Replacement	Exterior Doors - Hollow Metal - Original Building Renewal	B2030 - Exterior Doors	5 - Year five	Exterior Enclosure	2015	Nov 21, 2015		Open	Exterior Doors - Hollow Metal - Original Building	53,040
Copyright © 20	16 VFA, Inc. All rights res	served.		No	w 30,2016	7:52:55 AM				Page 4 of 11



Category	Requirement Name	Prime System	Priority	System Group	Action Year	Action Date	Anish Date	Status	Linked System	Requirement Cost
Replacement	Exterior Doors - Exterior Door Hardware - Entire School Renewal	B2030 - Exterior Doors	5 - Year five	Exterior Enclosure	2015	Nov 21, 2015	,,	Open	Exterior Doors - Exterior Door Hardware - Entire School	21,840
Replacement	Exterior Windows - Original Building Renewal	B2020 - Exterior Windows	6 - Year one SPW	Exterior Enclosure	2018	Nov 21, 2018		Open	Exterior Windows - Original Building	203,224
Replacement	Fencing & Gates - Chain-Link Fence 6 feet high Renewal	G204001 - Site Development - Fencing and Gates	4 - Year four	None Selected	2015	Jan 11, 2015		Open	Fencing & Gates - Chain-Link Fence 6 feet high	27,311
Replacement	Fire Alarm Systems - Original Building Renewal	D503001 - Communication and Security - Fire Alarm	4 - Year four	None Selected	2015	Jan 4, 2015		Open	Fire Alarm Systems - Original Building	65,525
Replacement	Fittings - Fittings and Equipment - Student Storage Lockers -Original Building Renewal	C1030 - Fittings	5 - Year five	Interior Construction and Conveyance	2015	Nov 21, 2015		Open	Fittings - Fittings and Equipment - Student Storage Lockers -Original Building	109,200
Replacement	Pittings - Millwork - Original Building Renewal	C103009 - Fittings - Millwork	5 - Year five	None Selected	2015	Nov 21, 2015		Open	Fittings - Millwork - Original Building	106,080
Copyright © 20	16 VFA, Inc. All rights res	erved.		Nov	30,2016	7:52:55 AM				Page 5 of 11



Category	Requirement Name	Prime System	Priority	System Group	Action Year	Action Date	Anish Date	Status	Linked System	Requirement Cost
Replacement	Fittings - Fittings and Equipment - Addition 1 Renewal	C1030 - Fittings	6 - Year one SPW	Interior Construction and Conveyance	2019	Nov 21, 2019	.,	Open	Fittings - Fittings and Equipment - Addition 1	36,400
Replacement	Fittings - Washroom Partitions - Original Building Renewal	C103002 - Fittings - Washroom Accessories	5 - Year five	None Selected	2015	Nov 21, 2015		Open	Fittings - Washroom Partitions - Original Building	49,500
Replacement	Floor Finishes - Carpet - Original Building Renewal	C302005 - Floor Finishes - Carpet	5 - Year five	None Selected	2015	Nov 21, 2015		Open	Floor Finishes - Carpet - Original Building	43,725
Replacement	Floor Finishes - Vinyl Floor Tiles - Original Building Renewal	C302015 - Floor Finishes - Vinyl Sheet	5 - Year five	None Selected	2015	Nov 21, 2015		Open	Floor Finishes - Vinyl Floor Tiles - Original Building	147,387
Replacement	Floor Finishes - Hardwood - Stage Renewal	C302003 - Floor Finishes - Wood	5 - Year five	None Selected	2015	Nov 21, 2015		Open	Floor Finishes - Hardwood - Stage	16,456
Replacement	Floor Finishes - Painted/Sealed Concrete Floor Renewal	C302007 - Floor Finishes - Painted Sealed Concrete	5 - Year five	None Selected	2015	Nov 21, 2015		Open	Floor Finishes - Painted/Sealed Concrete Floor	13,086
Replacement	Floor Finishes - Vinyl Floor Tiles - Addition 1 Renewal	C302015 - Floor Finishes - Vinyl Sheet	6 - Year one SPW	None Selected	2017	Nov 21, 2017		Open	Floor Finishes - Vinyl Floor Tiles - Addition 1	46,814
Copyright © 20	16 VFA, Inc. All rights rese	erved.		Nov	30,2016	7:52:55 AM				Page 6 of 11



Category	Requirement Name	Prime System	Priority	System Group	Action Year	Action Date	Rnish Date	Status	Linked System	Requirement Cost
Replacement	Gas Supply System - Original Building Renewal	D301002 - Energy Supply System - Natural Gas	4 - Year four	None Selected	2015	Jan 4, 2015		Open	Gas Supply System - Original Building	10,916
Replacement	General Purpose Room - Original Building Renewal	F106007 - General Purpose Room*	6 - Year one SPW	None Selected	1996	Jan 1, 1996		Open	General Purpose Room - Original Building	0
Replacement	Grounding Systems - Original Building Renewal	D509003 - Other Electrical - Grounding	6 - Year one SPW	None Selected	2016	Sep 18, 2016		Open	Grounding Systems - Original Building	8,685
Replacement	Heating/Chilling water distribution systems - Original Building Renewal	D304003 - Distribution Systems - Heated Water Distribution Systems	6 - Year one SPW	None Selected	2021	Sep 18, 2021		Open	Heating/Chilling water distribution systems - Original Building	48,001
Replacement	Interior Doors - Interior Door Hardware - Entire School Renewal	C1020 - Interior Doors	5 - Year five	Interior Construction and Conveyance	2015	Nov 21, 2015		Open	Interior Doors - Interior Door Hardware - Entire School	33,280
Replacement	Interior Doors - Wood Single Door and Hollow Metal - Original Building Renewal	C1020 - Interior Doors	5 - Year five	Interior Construction and Conveyance	2015	Nov 21, 2015		Open	Interior Doors - Wood Single Door and Hollow Metal - Original Building	87,360
Copyright © 20	yright © 2016 VFA, Inc. All rights reserved.			Nov	30,2016	7:52:55 AM				Page 7 of 11



Category	Requirement Name	Prime System	Priority	System Group	Action Year	Action Date	Rnish Date	Status	Linked System	Requirement Cost
Replacement	Landscaping Renewal	G2050 - Landscaping	6 - Year one SPW	Site	2005	Jan 1, 2005	,	Open	Landscaping	58
Replacement	Library Resource Centre - Original Building Renewal	F106003 - Library Resource Centre*	6 - Year one SPW	None Selected	1996	Jan 1, 1996		Open	Library Resource Centre - Original Building	0
Replacement	Lighting Equipment - Addition 1 Renewal	D5020 - Lighting and Branch Wiring	6 - Year one SPW	Electrical System	2020	Jan 4, 2020		Open	Lighting Equipment - Addition 1	8,603
Replacement	Lighting Equipment - Addition 1 Renewal	D5020 - Lighting and Branch Wiring	6 - Year one SPW	Electrical System	2017	Jan 4, 2017		Open	Lighting Equipment - Addition 1	9,090
Replacement	Lighting Equipment - Original Building - Exterior Lighting Renewal	D5020 - Lighting and Branch Wiring	6 - Year one SPW	Electrical System	2020	Jan 4, 2020		Open	Lighting Equipment - Original Building - Exterior Lighting	10,388
Replacement	Lighting Equipment - Original Building - Emergency Lighting Renewal	D502007 - Lighting and Branch Wiring - Emergency Lighting	4 - Year four	None Selected	2015	Jan 4, 2015		Open	Lighting Equipment - Original Building - Emergency Lighting	15,284
Replacement	Lighting Equipment - Original Building - Interior Lighting Renewal	D502003 - Lighting and Branch Wiring - Interior Lighting	4 - Year four	None Selected	2015	Jan 4, 2015		Open	Lighting Equipment - Original Building - Interior Lighting	293,731
Copyright © 20	16 VFA, Inc. All rights rese	erved.		N	ov 30, 2016	7:52:55 AM				Page 8 of 11



Category	Requirement Name	Prime System	Priority	System Group	Action Year	Action Date	Anish Date	Status	Linked System	Requirement Cost
Replacement	Main Switchboards - Original Building Renewal	D501003 - Electrical Service and Distribution - Main Switchboard	6 - Year one SPW	None Selected	2016	Sep 18, 2016	,	Open	Main Switchboards - Original Building	28,320
Replacement	Other Communications & Alarm Systems - Original Building Renewal	D503099 - Communication and Security - Other	6 - Year one SPW	None Selected	2020	Sep 18, 2020		Open	Other Communications & Alarm Systems - Original Building	12,545
Replacement	Parking Lots - Asphalt Paved Surfaces Renewal	G2020 - Parking Lots	5 - Year five	Site	2015	Nov 21, 2015		Open	Parking Lots - Asphalt Paved Surfaces	49,140
Replacement	Pedestrian Paving – Asphalt Paved Walkways Renewal	G2030 - Pedestrian Paving	5 - Year five	Site	2015	Nov 21, 2015		Open	Pedestrian Paving - Asphalt Paved Walkways	16,372
Replacement	Playing Fields - Paved Playing Field Renewal	G2040 - Site Development	5 - Year five	Site	2015	Nov 21, 2015		Open	Playing Fields - Paved Playing Field	32,760
Replacement	Playing Fields - Unpaved Playing Field Renewal	G2040 - Site Development	6 - Year one SPW	Site	2005	Jan 1, 2005		Open	Playing Fields - Unpaved Playing Field	0
Replacement	Plumbing Fixtures - Original Building Renewal	D2010 - Plumbing Fixtures	4 - Year four	Plumbing System	2015	Jan 4, 2015		Open	Plumbing Fixtures - Original Building	229,000
Copyright © 20	16 VFA, Inc. All rights rese	No	ov 30, 2016	7:52:55 AM				Page 9 of 11		



Copyright © 2016 VFA, Inc. All rights reserved.

Requirement List Report By Category

Page 10 of 11

Date: December 13, 2016

Requirement Name	Prime System	Priority	System Group	Action Year	Action Date	Pinish Date	Status	Linked System	Requirement Cost
Security Systems - Original Building Renewal	D503008 - Communication and Security - Security	6 - Year one SPW	None Selected	2018	Sep 18, 2018	,	Open	Security Systems - Original Building	8,554
Signage - Non- Illuminated Double Face Renewal	G204005 - Site Development - Signage	5 - Year five	None Selected	2015	Nov 21, 2015		Open	Signage - Non- Illuminated Double Face	11,642
Terminal & Package Units - Original Building Renewal	D3050 - Terminal and Package Units	4 - Year four	HVAC System	2015	Jan 4, 2015		Open	Terminal & Package Units - Original Building	29,484
Underground Utilities Renewal	G30 - Site Mechanical Utilities	6 - Year one SPW	Site	2006	Jan 1, 2006		Open	Underground Utilities	112
Wall Finishes - Paint Wall Covering - Entire School Renewal	C301006 - Wall Finishes - Vinyl (Wall Pap <i>e</i> r)	5 - Year five	None Selected	2015	Nov 21, 2015		Open	Wall Finishes - Paint Wall Covering - Entire School	163,805
									3,575,717
Study [Air Distribution, Heating & Cooling - Original Building]	D304001 - Distribution Systems - Air Distribution, Heating & Cooling	3 - Year three	None Selected	2015	Jan 1, 2015		Open	Air Distribution, Heating & Cooling - Original Building	10,920
	Security Systems - Original Building Renewal Signage - Non- Illuminated Double Face Renewal Terminal & Package Units - Original Building Renewal Underground Utilities Renewal Wall Finishes - Paint Wall Covering - Entire School Renewal Study [Air Distribution, Heating & Cooling - Original	Security Systems - Original Building Renewal Signage - Non-Illuminated Double Pace Renewal Signage Terminal & Package Units - Original Terminal and Building Renewal Package Units - Original Uniter Strong Units - Original Package Units Underground Utilities Renewal Units - Original Unities Wall Finishes - Paint Wall Covering - Entire School Renewal Study [Air Distribution, Heating & Cooling - Original Building] Study [Air Distribution Systems - Air Distribution, Heating & Cooling - Original Systems - Air Distribution, Heating & Cooling - Original Sullding]	Security Systems - Original Building Renewal Communication and Security - Security Signage - Non- G204005 - Site Development - Signage	Security Systems - Original Building Communication and Security -	Security Systems - D503008 - 6 - Year one SPW None Selected 2018 Original Building Communication and Security - Security Signage - Non- G204005 - Site Development - Signage - S	Security Systems - O503008 - G - Year one SPW None Selected 2018 Sep 18, 2018 Communication and Security - Security Signage - Non- G204005 - Site Development - Signage - Signa	Security Systems - Official Renewal Signage - Non- G204005 - Site Development - Signage - Norginal & Package Units Underground Utilities Renewal Wall Finishes - Paint Wall Covering - Entire School Renewal Study [Air Distribution, Heating & Cooling - Original Building Communication and Security - Security S	Security Systems - Original Building Renewal Signage - Non- Signag	Security Systems - D503008 - G - Year one SPW Original Building Renewal Signage - Non- Belected Signage - Non- Belected Signage - Security - Se

Nov 30, 2016 7:52:55 AM



Date: December 13, 2016

Category	Requirement Name	Prime System	Priority	System Group	Action Year	Action Date	Anish Date	Status	Linked System	Requirement Cost
Study	Study [Domestic Water Distribution - Original Building]	D202001 - Domestic Water Distribution - Pipes and Fittings	3 - Year three	None Selected	2015	Jan 1, 2015		Open	Domestic Water Distribution - Original Building	10,920
Study	Study [Und <i>e</i> rground Utilities]	G30 - Site Mechanical Utilities	3 - Year three	Site	2015	Jan 1, 2015		Open	Underground Utilities	10,920
Study										32,760
Eastwood Po 5755-1-575:	rublic School, Building ID 5-1									4,034,357
Eastwood P	Public School, Campus ID	5755								4,034,357
Greater Ess	reater Essex County District School Board									
Summary										4,034,357

Copyright $\,^{\mbox{\scriptsize \mathbb{O}}}$ 2016 VFA, Inc. All rights reserved.

Nov 30, 2016 7:52:55 AM

Page 11 of 11

Summary of five previous year's enrolment and 10-year enrolment projection by grade and program.

5 Year FTE Enrolment History

Grade	2011	2012	2013	2014	2015
JK	24	39	25	21	23
SK	26	25	33	28	25
01	38	24	26	28	24
02	32	40	26	31	29
03	34	31	35	21	31
04	23	37	29	31	20
05	31	27	36	32	30
06	37	27	28	36	30
07	38	36	26	25	32
08	46	38	33	26	26
Total	329	324	297	279	270

Enrolment Actual - September 26, 2016

Year	JK	SK	01	02	03	04	05	06	07	08	Total
2016	21	27	22	27	29	32	21	32	27	33	271

10 Year Enrolment Projections

Grade	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026
JK	19	21	19	19	19	19	19	19	19	19
SK	22	19	20	19	19	19	19	19	18	18
01	28	24	18	21	19	19	19	19	19	19
02	30	28	28	20	21	20	20	20	20	20
03	28	29	27	27	20	21	20	17	17	17
04	27	26	27	25	25	19	20	19	17	17
05	32	27	26	28	25	25	19	20	19	17
06	22	32	27	27	27	25	25	19	20	19
07	33	22	33	27	26	27	25	25	19	20
08	29	33	22	33	27	26	27	25	25	19
Total	270	261	247	246	228	220	213	202	193	185